



Digitizers

Serial number	Model	Conet PID	Daisy node	VME address	
553	V1730B	25507	0	0x2003	
416	V1730B	25507	1	0x2002	
549	V1730B	25507	2	0x2001	next to the bridge
30639	V1730SB	32636	0	0x2006	
30640	V1730SB	32636	1	0x2005	
30641	V1730SB	32636	2	0x2004	broken PLL


Noise readout




Noise readout




Noise readout




Noise readout




Noise readout




Pulse readout




Pulse readout




Pulse readout




Pulse readout



Pulse readout



Pulse readout



- ▶ Empty data files — fixed.
- ▶ Timings — need to reconfigure the digitizers to stop propagating software trigger to TRG-OUT.
- ▶ Cannot talk to high voltage boards: VME bus error.